

APPENDIX 3

HYDRO GROUP AIR STRIPPING INSPECTION REPORTS



ENVIRONMENTAL PRODUCTS DIV.

December 9, 1992

Mr. Brian Fitzgerald
City of Norwalk
First Taxing District Water Department
POB 27
3 Belden Avenue
Norwalk, CT 06857

Re: Tower Inspection at Layne-Dearing Well Field

Dear Mr. Fitzgerald:

Please find enclosed the introductory inspection report for the inspection services performed by Hydro Group, Inc. on October 14, 1992 for the Layne-Deering Well Field facility.

As indicated in the inspection report there were several items that were noted during inspection of the air stripping facility that should be monitored, specifically:

- The blower belts were loose and cracked.
- The tower internals -- packing, packing support tray, and sump bottom -- were coated with manganese.
- There was some pitting present on the tower sump bottom.


The blower belts should be replaced and the manganese build up monitored. To prevent further pitting from occurring in the air stripping tower, the pitted surfaces can be sandblasted and coated with a high build epoxy. Hydro Group, Inc. would be pleased to provide a proposal for the work to be done if you are interested.

In order to monitor the manganese coating on the tower internals for potential fouling problems and to keep up to date on the pitting of the tower floor, a follow-up inspection should be scheduled in six to twelve months. Attention to these problems would be in your best interest to insure the continuing smooth operation of your air stripping facility.

Thank you for your cooperation and assistance with this inspection.

Sincerely yours,

HYDRO GROUP, INC.
Environmental Products Division

A handwritten signature in cursive script, appearing to read "Michelle Saczynski".

Michelle D. Saczynski
Engineer

MDS/ycb
Enclosures
cc: Ken C. Gaynor

INSPECTION REPORT #2922-92-1

NORWALK, CT
ORIGINAL JOB NO. 2342-82

Prepared for

CITY OF NORWALK
FIRST TAXING DISTRICT WATER DEPARTMENT

Prepared By:

Hydro Group, Inc.
Environmental Products Division
97 Chimney Rock Road
Bridgewater, NJ 08807
(908) 563-1400

NOVEMBER, 1992

HYDRO GROUP, INC.
ENVIRONMENTAL PRODUCTS DIVISION
FIELD INSPECTION REPORT

REPORT #2922-92-1

SITE: City of Norwalk, CT
FACILITY: Layne-Dearing Well Field Tower
DATE OF INSPECTION: October 14, 1992
INSPECTED BY: Michelle D. Saczynski & Kimberlie Staheli
DATE OF REPORT: December 9, 1992

INTRODUCTION

The referenced facility was inspected for the City of Norwalk First Taxing District Water Department as part of the operation and maintenance program for the treatment system. Inspection of the treatment system consisted of examining the following areas:

- 1) Packed Tower:
 - interior through manways
 - packed tower internals
 - packing media
 - exterior
 - effluent sump
- 2) Blower
 - speed, airflow, static pressure
 - belts, motor and blade
 - alignment
 - connections
 - air filters
 - voltage and amperage draws

These items are described in the inspection log. Special conditions of operation are noted below, as well as conclusions and recommendations for future system operation.

HYDRO GROUP, INC.
INSPECTION REPORT

Performed for

City of Norwalk
First Taxing District Water Department

AIR STRIPPER

- | | | |
|----|--|-----|
| 1. | Were there any leaks in tower structure? | No |
| 2. | Was there any buildup on the air discharge screens? | No |
| 3. | Were there any leaks at tower body flanges, manways, piping or duct flanges? | No |
| 4. | Was piping leaking, weathered or corroded? | No |
| 5. | Was anchoring system secure? | Yes |
| 6. | Were there any tears in blower ducts? | No |
| 7. | Was all tubing, valves, and instrumentation in place? | Yes |
| 8. | Were tower manways removed to inspect tower internals? | No |

The bottom manway was not removed completely because there was no screen to retain the packing media.

9. Describe condition of internals, packing and shell:

a. Bottom Manway

The packing that was visible when the manway was partially opened had manganese staining.

b. Tower Sump

There was a uniform black coating on the bottom of the tower that extended about 2" up the tower wall. Visible through this coating were pits ranging from 1/4" to 1/2" wide and about 1/16" deep. The pitting action was not present on the tower wall. The packing on the support tray had a spotty manganese coating -- not all of the packing surfaces were coated.

BLOWER

- | | | | |
|----|---|--|-----|
| 1. | Check blower rpm: | 791 rpm | Yes |
| 2. | Check motor rpm: | Rated - 1760 rpm;
Measured - 1778 rpm | Yes |
| 3. | Check blower motor amperage draw: | 460 V | Yes |
| 4. | Check blower motor current draw: | 25 A | Yes |
| 5. | Check blower belt for cracking, wear or stretch | | Yes |
- Severe cracking in the belts was noted.
- | | |
|--|----|
| Is belt suitable for continued operation? | No |
| Belts need to be replaced. | |
| Was belt adjusted, aligned, tightened or replaced? | No |

GENERAL

1. Check for loose bolts on body flanges, manway covers, blower mount, etc. Tighten if necessary Yes
2. Report any general comments regarding the packed column, blower, etc.
Tower packing had manganese staining, but not enough to restrict water flow through the tower. The blower belts need replacing. Blower ductwork tight and in good condition.
3. Water quality data updated? No

INSPECTION DATE October 14, 1992

INSPECTOR(S) Michelle D. Saczynski & Kimberlie Staheli

INSPECTOR'S SIGNATURE *Michelle Saczynski*

SUMMARY

- 1) Tower opened and inspected for fouling, manganese buildup noted.
- 2) Blower belt inspected, and founded to be cracked and loose.
- 3) Slight pitting on tower floor.
- 4) Manway gasket in good condition.

RECOMMENDATION

- 1) Schedule a follow-up inspection to monitor the manganese deposition for potential packing fouling problems and to track the pitting taking place in the tower basin.
- 2) Replace the blower belts.
- 3) If you wish to take action on the pitting in the tower sump, sandblast the pitted surfaces on the tower sump bottom and coat with a high build epoxy. If coating is put off for now, it is strongly recommended that the tower be re-examined in 6 to 12 months to evaluate if changes in the pitting corrosion have occurred.

PHOTO DESCRIPTIONS

- 1) Packing support Tray -- note the non-uniform black manganese stains on the support tray and the packing visible an the support tray.
- 2) Tower Basin -- note the silver colored pits visible through the uniform manganese coating on the bottom of the sump.




Photo #1




Photo #2

AIR STRIPPING SYSTEM INSPECTION REPORT

3105-95-1

NORWALK, CT SITE

ORIGINAL JOB # 2342-82

PREPARED BY:



HYDRO GROUP, INC.
ENVIRONMENTAL PRODUCTS DIVISION
CHIMNEY ROCK ROAD
BRIDGEWATER, NJ 08807
908-563-1400
MAY, 1995

*Fax 732-563-1396
John Balla*

2.5

AIR STRIPPING SYSTEM INSPECTION REPORT
REPORT # 3105-95-1

SITE: Norwalk, CT
FACILITY: Deering Well Field
DATE OF INSPECTION: 04/25/95
INSPECTOR: Kenneth Wigg
DATE OF REPORT: May 2, 1995

INTRODUCTION

The referenced facility was inspected for Norwalk, CT as part of the operation and maintenance program for the water treatment system. Inspection of the treatment system consisted of examining the following areas:

SYSTEM EQUIPMENT:

- 1) Packed Tower
 - tower shell
 - tower foundation and clearwell
 - internals
- 2) Blower
 - speed, airflow, static pressure
 - voltage and amperage draws
 - belts, motor and blade
 - sheave alignment
 - connections

SYSTEM PERFORMANCE:

Water and air flow rate measurements were taken and compared to original system design parameters.

These items are described in the inspection log. Special conditions of operation are noted below, as well as conclusions and recommendations for future system operation.

AIR STRIPPING SYSTEM INSPECTION REPORT

Performed for
Deering Well Field
Norwalk, CT

SYSTEM EQUIPMENT

AIR STRIPPING TOWER SHELL	
1. Were the tower structures free of leaks?	YES
2. Were air outlet screens clean and unobstructed?	YES
3. Were manways, tower body flanges, piping, and duct flanges free of leaks? If no, describe: The upper body flange leaked at a high flow rate of 4.9 MGD.	NO
4. Were the manway and body flange bolts tight?	YES
5. Were there any signs of corrosion? If yes:	YES
a. Where? Sump floor and distributor tray *.	
b. Type: Sump Floor - Exfoliation	
c. Pit Depth: Sump Floor - 1/32"	
d. Number of pits per unit area: Sump Floor - 2 per square inch	

* Distributor tray pits could not be measured.

TOWER FOUNDATION/CLEARWELL	
1. Was anchoring system secure?	YES
2. Was tower level?	YES
3. Was tower foundation intact?	YES

PIPING AND DUCTWORK	
1. Was piping free of leaks and/or corrosion?	YES
2. Were blower ducts intact and free of tears?	YES
3. Were flanged connection bolts tight?	YES
4. Check / replace any gasket material if necessary?	YES/ checked

BLOWER AND ACCESSORIES	
1. Were blower supports and housing free of corrosion and tight?	YES
2. Were air inlet screens clean and unobstructed?	YES
3. Were blower belts in good operational condition?	YES

AIR STRIPPING TOWER INTERNALS	
1. Manways removed to inspect tower internals?	YES
2. Check/replace any gasket material if necessary?	YES/ checked

Describe condition of internals, packing and shell:

a. Manway # 1 (location: Top of Air Stripping Tower)

Manway #1 allowed access to the area above the mist eliminator. The mist eliminator was shifted out of the way to inspect the distributor tray surface and the top of the packed bed. The distributor tray and visible packing were slightly stained black with manganese oxide. No heavy build-up was evident. There were some pit formations present on the distributor tray surface.

b. Manway # 2 (location: Bottom of Packed Bed)

Since there was no packing retaining screen over the manway, the cover was only cracked open. From that view the packing appeared to be slightly stained with manganese oxide.

c. Tower Sump (Accessed through air duct)

Pits were noted on the sump floor (see page 3). The packing visible on the support plate and the sump floor were stained with manganese oxide.

GENERAL:

General comments on equipment condition.

The system equipment was in overall good condition. The tower connections were tight and free of leaks, with the exception of the upper body flange; the flange leaked at high water flow rates. There were some pits present on the distributor tray and sump floor surfaces, however the pits appeared to be unchanged from the last inspection in 1993.

INSPECTION DATE: 04/25/95

INSPECTOR: Kenneth Wigg

INSPECTOR'S SIGNATURE



INSPECTION SUMMARY

BLOWER PERFORMANCE	Rated	Measured
1. Blower RPM	795	810-820
2. Motor RPM	1,765	1,760
3. Motor Amperage Draw: AMPS	48/24	22
4. Motor Voltage	230/460	490
5. Motor HP	20	18.6
6. Blower Airflow Rate: CFM (Determined from manufactures fan curves.)	23,400	24,000
7. Static Pressure: inches of water column	4.0	3.9
8. Static Pressure across packing: in. w.c.	2.63	2.4
9. Are blower belts suitable for continued use?	Yes	
10. Are shaft, motor and sheave(s) aligned?	Yes	

SYSTEM EQUIPMENT SUMMARY	
EQUIPMENT COMPONENT	COMMENTS
Tower Shell	Excellent condition, with the exception of some pits on the distributor tray and tower sump floor.
Tower Internals	Good condition. There were some manganese oxide stains on the visible packing surfaces and tower sump floor.
Piping and Ductwork	Excellent condition.
Blower and Accessories	Good condition.

SYSTEM PERFORMANCE SUMMARY		DESIGN	MEASURED *
1)	Water flow (gpm):	1,750	1,425-3,400
2)	Air flow (cfm):	23,400	25,000-22,000
3)	Static pressure (in. w.c.):	4.0	3.7-4.8

- * With four wells on: 3,403 gpm → s.p. = 4.8", Amp Draw = 20A
 With three wells on: 3,055 gpm → s.p. = 4.7", Amp Draw = 20 A
 With two wells on: 2,013 gpm → s.p. = 4.3", Amp Draw = 21 A
 With one well on: 1,425 gpm → s.p. = 3.8", Amp Draw = 22 A

RECOMMENDATIONS

The air stripping system was in excellent condition. Three minor problems were noted during the inspection. They were as follows:

1. Leaking upper body flange at high water flow rates.
2. Manganese oxide stains on the visible packing and sump floor.
3. Pit formations on the distributor tray and sump floor.

To prevent the upper body flange from leaking, the gasket material can be replaced. Hydro Group, Inc. can provide you with a quote to do this maintenance work if you are interested.


An annual inspection program is recommended to monitor the manganese deposition and the pit formations for potential problems.

PHOTO DESCRIPTIONS

1. Distributor Tray and Top of Packed Bed - Note the dark manganese oxide stains on the tray and packing surfaces, and the light colored pit formations on the tray.
2. Bottom of Packed Bed - Note the dark colored manganese oxide stains on the support plate and packing.
4. Tower Sump - Note the light colored pit formations on the sump floor.


File # 95000264

Photo 1 ->



<- Photo 2

Photo 3 ->



APPENDIX 4
DPH INSPECTION REPORTS

Mailed 12/24

26 50



STATE OF CONNECTICUT

DEPARTMENT OF HEALTH SERVICES

December 24, 1992

Mr. Brian A. Fitzgerald
Norwalk First District Water Department
3 Belden Avenue, P.O. Box 27
Norwalk, CT 06852

Subject: Distribution Inspection Report

Dear Mr. Fitzgerald:

The Department conducted an inspection of the Norwalk First District Water Department's (NFDWD) distribution on September 16, 1992. The inspection was conducted with Fred Petrini of NFDWD.

Based on the inspection and a review of the Department's files the following conclusions and recommendations have been rendered:

1) The Filbert Street, Bayne Street, and Spring Hill tanks have recently been painted. NFDWD is requested to forward information on the interior paint products used and the dates when these projects were completed.

2) The overflow on the West Rocks elevated tank must be screened.


3) NFDWD should inspect all tank overflows and vents to verify that they are appropriately screened or equivalently protected.

4) A chlorine treatment system is used at the Spring Hill pump station to boost chlorine levels in the associated high service area. NFDWD should indicate the normal feed rates (i.e. ppm) of chlorine for this station. NFDWD should also indicate if a flow switch is used to control the chemical feed pump on and off, as is stated in the attached Department's policy.

5) An update on the present operation of the Silvermine Crossing's water supply arrangement with NFDWD should be forwarded to this office.

6) A brief outline of NFDWD's flushing program should be sent to this office.

7) At the time of inspection it was indicated that new pumps are planned to be installed at the Spring Hill pump station. The Department should be notified when the project is completed and of the operational discharge capacities of the new pumps.



STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH AND ADDICTION SERVICES

NAME: Mr. Brian Fitzgerald

DATE: August 8, 1995

ADDRESS: P.O. Box 27, 3 Belden Avenue
Norwalk, CT 06856

UTILITY: Norwalk First Taxing District TOWN: Norwalk

(X) For your information.

() Please note special recommendations.

() Resampling requested.

(X) For necessary action.

(X) Remarks. The Norwalk First Taxing District is urged to
review and implement the items stated in the attached
inspection report. A written response addressing each item
and indicating dates of implementation must be submitted to
this office before September 30, 1995.

A handwritten signature in cursive script, appearing to read "H. C. Adams".

Henry C. Adams
Sanitary Engineer 3
Water Supplies Section

HA/sr
wp51/inspect

cc: Timothy Callahan, Norwalk Director of Health
Judith Sartucci, DPH LHA



August 8, 1995

SUBJECT: NORWALK, CT: INSPECTION OF THE Brian Fitzgerald
NORWALK FIRST TAXING DISTRICT P.O. Box 27
PUBLIC WATER SYSTEM ON 3 Belden Avenue
3/22/95 & 4/5/95. Norwalk, CT 06856
cc: Timothy Callahan
Norwalk DOH

From: Sheryl C. Robbins *SK*
Sanitary Engineer 2
Water Supplies Section

Inspected with: William Lahey and Franco Chieffalo

DESCRIPTION OF FILTRATION PLANT AND TREATMENT FACILITIES

The facility is located at Valley Road in New Canaan and has a maximum design flow rate of 7.2 million gallons per day (MGD). At the time of inspection approximately 6.6 MGD from Milne Lake was being treated.

The sources of supply for this facility consist of Scotts Reservoir, Browns Reservoir, John D. Milne Lake, and Grupes Reservoir arranged in a north to south series, respectively. Grupes Reservoir presently was not being used, but is the facility's second distribution reservoir from which water can flow into the facility. The safe yield of these sources, as indicated in the Norwalk First Taxing Department's (NFTD) 1994 water supply plan is 4.0 MGD.

The treatment process at the time of inspection consisted of: chemical pre-treatment with Polyaluminum Chloride (PACl); rapid mixing in two parallel basins having paddle mixers; flocculation in two parallel baffled basins; sedimentation in two parallel settling tanks containing baffles in the center section and parallel plate settling grids in the discharge end; Magnifloc injection after sedimentation; filtration in four parallel mixed media filters (20" anthracite, 10" sand, & 10" gravel); chemical post-treatment with fluoride (hydrofluosilicic acid), chlorine gas, caustic (sodium hydroxide), and zinc orthophosphate; followed by storage in a 0.75 MG clearwell. The water flow through this treatment process is by gravity. Backwashing lasts 9-10 minutes and is done every 22 hours or if breakthrough occurs. The filters are drained each month to inspect for mudballing or other signs of filter problems. The media life is 7-9 years.

Additional treatment not in use during the inspection, nor has it been used for many years, is the dry chemical addition of carbon.

The treatment facility is equipped with two parallel pumps, rated at approximately 350 gpm, for transferring water from the clearwell to a 110,000 gallon backwash storage tank. This tank is located on the hill behind the facility to supply the necessary elevation head to permit backwashing of the filters by gravity. Backwash water and all wastewater generated at this facility enters a gravity sewer main for transmission to a Norwalk sewage treatment plant. A second pair of parallel pumps is located at this facility for pumping water from the clearwell to the building's hydropneumatic system which has two tanks approximately 400 gallons each. The final set of pumps at this facility is for boosting flows to the distribution system. These booster pumps are rated at 1 pump = 4.8 MGD, 2 pumps = 5.6 MGD, 3 pumps = 6.8 MGD, or the 4th pump alone = 8.0 MGD. Two automatically starting generators are available at this facility, each having the capability to run all operations.

A booster station is located downhill of this facility for supplying approximately 60 homes in New Canaan. This station is equipped with two parallel variable speed pumps, in order to maintain pressure, since there is no distribution storage.

DESCRIPTION OF WELL FIELD AND TREATMENT FACILITIES

The NFTD's Kellogg-Deering well field is located between Spring Hill Avenue and the Norwalk River. The well field facilities consist of 4 active wells (i.e. Layne 1R-L1R, Layne 2-L2, Deering 1-D1, Deering 2-D2), 2 abandoned wells (i.e. Smith caisson and the Layne 1-L1), a packed column aeration tower, 750,000 gallon inground concrete clearwell, pump station, and treatment station.

The 4 active wells are manually controlled at the well field to pump into the top of the aeration tower. Water flows by gravity through the aeration tower to the 750,000 gallon clearwell. The pump station is located on top of the clearwell and consists of 3 parallel transfer pumps (i.e. 2-1.8 MGD and 1-2.5 MGD) and controls. The transfer pumps are controlled at the filter plant (can be manually overridden at the well field) to pump water through the well field's treatment station and into the distribution system. In the treatment station the water main discharging to the distribution system is injected with chlorine, hydrofluosilicic acid, and zinc orthophosphate. Also located in the treatment station are the controls for the wells, a venturi meter used to measure the well field's production and to pace the proportional flow chemical feed pumps, 2 diesel generators which would power all the equipment in the wellfield with the exception of wells D1 and D2, and pH adjustment equipment (sodium hydroxide) which presently is not used.

DESCRIPTION OF DISTRIBUTION SYSTEM AND TREATMENT FACILITIES

The distribution system is divided into three pressure zones. The West Rocks High Service area consists of the West Rocks booster pump station, the Silvermine Crossing booster pumps, the West Rock elevated tank, and the Bayne Street standpipe. The main low pressure zone is served by the Filbert Street tank and the Spring Hill standpipe. The Spring Hill High Service area consists of the Spring Hill booster pump station with chlorination and the Spring Hill elevated tank.

WATER QUALITY

There were no water samples collected at the NFTD system at the time of inspection. Based on results of water samples for the past year, the water is of good quality and meets the current State and Federal Standards for all parameters tested, except for distribution lead and copper.

The Lead Action Level was exceeded during the January - June 1993 monitoring period. NFTD has complied with all requirements to date and altered the chemical treatment (Shan-no-Cor dosage). The first follow-up monitoring results indicate the new treatment is working (Lead 90% = 0.010 mg/l).

The 5/17/95 raw water analyses for active wells D1, D2, L1R, and L2 indicate levels of trichloroethylene in excess of the maximum contaminant level (MCL) of 5 ug/l. In addition cis-1,2-dichloroethylene, 1,1,1-trichloroethane, 1,1-dichloroethylene, tetrachloroethylene, and 1,1-dichloroethane have been detected. The aeration tower removes these compounds down to non-detectable limits based on current quantification levels.

CONCLUSIONS AND RECOMMENDATIONS

FILTRATION PLANT AND TREATMENT FACILITIES

1. The filter plant was treating approximately 6.6 MGD at the time of the inspection. The NFTD's Water Supply Plan indicates a safe yield of 4.0 MGD of the sources supplying the filter plant. Please submit an explanation of NFTD's position on this overdrafting of the resources.
2. The opening near the ceiling in the hallway/chlorination room wall must be sealed to prevent chlorine gas from entering the treatment facility in the event of a leak.

3. NFTD must seal the hatch to the filter plant clearwell in accordance with the Connecticut Public Health Code (PHC) Section 19-13-B102(f)(3). There was a hole in the hatch next to the float gauge opening through the hatch.
4. NFTD must repair and properly screen the broken vents for the filter plant clearwell and backwash storage tanks to prevent entrance of surface water runoff, insects, and debris in accordance with PHC Section 19-13-B102(f)(3).
5. NFTD must remodel the hard-plumbed make-up water line for the phosphate treatment in the filter plant with an adequate air gap to prevent back-siphonage in accordance with PHC Section 19-12-B38b.
6. The bulk storage fill lines at the filter plant warehouse were not locked. These should be locked to prevent unauthorized entrance or tampering to the chemical storage tanks and treatment of the water.
7. NFTD should provide containment at the bulk storage fill lines to trap accidental spills or overflows.
8. The entrance to the chlorination room at the filter plant has been relocated as approved by this Department. The exhaust fan in the chlorination room should turn on in conjunction with the light switch or the opening of the entrance door. This recommendation was presented in the 5/1/90 inspection report.
9. All chemical injection lines and tanks should be labelled with the chemical contained in them. (i.e. Alum was replaced with Polyaluminum Chloride)
10. This Department recommended the installation of deadman valves or other mechanisms on all day tanks to prevent overflow. NFTD has installed high level alarms on all day tanks to alert the operators to any potential overflow.

WELL FIELD AND TREATMENT FACILITIES

11. NFTD must seal the Well L1R well cap (where the pressure gauge enters the well) in accordance with PHC Section 19-13-B51j.
12. NFTD must extend the end of the sump discharge lines at Wells D1 and L2 to at least 50' from the well to meet the minimum separating distance required from surface water in accordance with PHC Section 19-13-B51d.
13. NFTD must screen the Well L2 pit vent in accordance with PHC Section 19-13-B51i.

14. NFTD should provide secondary containment for the zinc orthophosphate day tank at the wellfield treatment plant.
15. Each blowoff for the wells have a clapper on the discharge near the Norwalk River. NFTD should consider altering the discharge end to prevent entry of river water into the lines when the river level rises.
16. Temporary threaded taps were installed to facilitate testing for Groundwater Under Direct Influence of Surface Water. If these taps are not removed upon completion of the tests, they should be replaced with smooth, threadless, chrome-plated sample taps or hose bibb vacuum breakers should be installed. The taps should be at least 12 inches off the ground floor, pointed downward, and clear of any obstructions.

DISTRIBUTION SYSTEM AND TREATMENT FACILITIES

17. NFTD must routinely inspect all storage tank overflows and vents to verify that they are screened and protected in accordance with PHC Section 19-13-B102(f).
18. NFTD must continue to periodically flush the distribution system to maintain it free from sediment and other matter in accordance with PHC Section 19-13-B102(f)(5).
19. Representative weekly meter readings of instantaneous flow rate and total quantity of water must be recorded in accordance with PHC Section 19-13-B102(n).
20. The West Rocks elevated tank and the Bayne Street standpipe showed evidence of some rusting on the exterior surface. The Filbert Street tank paint was peeling and mildew/dirt was evident on the tank exterior surface. These tanks should be inspected to determine the integrity of the tank materials and repaired as necessary.
21. One riser base of the Filbert Street tank was cracked at the time of the inspection. NFTD must inspect the base to determine the integrity of the support and repair as necessary.
22. This Department recommended flow totalizing meters be installed at all active interconnections with the Bridgeport Hydraulic Company and the Norwalk Second Taxing District Water Department in the 5/1/90 inspection report. Please verify the status of the meter installations.

23. Consumption of 164 gpd per customer seems excessive. Please provide an explanation for this high consumption rate.

In general, the system appears to be in fair condition. Mr. Lahey and Mr. Chieffalo were very knowledgeable and cooperative. Items #2-#5, #11-#13, and #17 listed in this report must be corrected immediately. A written response to the items listed in this report must be submitted before September 30, 1995.

INSPECTION OF PUBLIC WATER SUPPLY

DATE: _____

NAME OF UTILITY: NORWALK FIRST TAXING DISTRICTINSPECTED WITH: BILL LANEY & FRANCO CHIEFFALOINSPECTED BY: S. POIRYAS

SOURCE INFORMATION

SYSTEMATIC FLUSHING: ANNUALLY IN SPRINGINTERCONNECTIONS: BHC NORWALK SECOND TAX DIST

SOURCE	COMMENTS	WELL				pumping capacity (GPM)	safe yield (GPD)	distance to nearest source of pollution	type of pollution
		metered	type	diameter	depth				
SCOTT'S RESERVOIR	STORAGE				55.7				
BROWN RESERVOIR	STORAGE				290.4		40M		
JOHN D MILNE LAKE	DISTRIBUTION				541.4				
GRUPES RESERVOIR	DISTRI - NOT IN USE				53.95				
L1 R - LAINE 1 REPLACEMENT	ACTIVE - ABOVE GRADE	YES	GRAVEL PACKED	16"	57'	1320	1000 GPM	~200'	NORWALK RIVER
L2 - LAINE 2	ACTIVE - IN PIT	HINTER	GRAVEL PACKED	20"	44'	2.2 MGD	375 M	50'	NORWALK
D1 DEERING 1	ACTIVE - IN PIT	METER	GRAVEL PACKED	20"	84'	1.6 MGD			
D2 - DEERING 2	ACTIVE - IN PIT	16W-R	GRAVEL PACKED	20"	85'	2.6 MGD			

INFO FROM DEC. 1994 WATER SUPPLY PLAN

7.75 TOTAL

TREATMENT

TYPE	RATE OF DOSAGE	POINT OF INJECTION	FREQ. OF TESTING	TESTING EQUIPMENT	AMT & TYPE OF CHEM(S)	SAFETY EC
SEE ATTACHED SHEETS						

DISTRIBUTION

BOOSTER STATION:		EST. POPULAT. SERVED	YEARLY AVE DAILY CONSUMP. (GPD)	PER. CAPITA CONSUMP. (GPCD)	EST. SAFE YIELD OF SOURCES (GPD)	MAXIMUM HOUR DEMAND (GALS.)	GALLONS AVAIL MAXIMUM HOUR	NUMBER OF SERVICES	NUMBER OF METERS	STORAGE TANKS (QTY/SIZE)	TYPE OF STORAGE (PRESS./ATM.)	TRANSFER PUMPS (QTY/SIZE)
WEST ROCKS HIGH & SPRING HILL HIGH SERVICE PUMP STATION												
TOTAL		38,502	6.3 M	2164	7.75 MGD	3(6.3) = 2.1 M		216,000 RESIDENTIAL TOTAL	NOT INDICATED	1/6.75 MG	ATM - CLEARWELL	1/4.5 M
WEST ROCKS		7,200 W.R.	1.2 M W.R.			400,000 W.R.	1217,000	1000 W.R.		1/0.75 MG	WELLFIELD	1/1.5 M
SPRING HILL		3,200 S.H.	0.5 M S.H.			175,000 S.H.	206,800	800 SPRING HILL		1/0.1 MG	ATM - WEST ROCK	1/1.5 M
MAIN		28,100	4.6 M							1/1.0 MG	ATM - BAYVIEW	1/1.0 M
TOTAL						1,525,000	3.7 M +			1/1.0 MG	ATM - FILBERT ST	1/1.0 M
										1/0.1 MG	ATM - SPRING HILL	2/2.0 M
										1/3.0 MG	ATM - SPRING HILL	1/3.0 M

COMMENTS:


Handwritten notes:

NOT TO SCALE


REVISED - 11/22/10 J. C. B.

INSPECTED 2/21/10 J. C. B.

MILNE LAKE RESERVOIR FILTRATION PLANT



Warehouse:






Water Treatment Plant
- brick bldg.

- front side

Valley Road


NOT TO SCALE

1105 FELTED 2/28/50 J. C. B. 5A




ATKINALL PLANT TRAINING GUIDE
NOT TO SCALE

REVISED / INSPECTED 3/22/15 S.M.B.
 INSPECTED 2/27/20 J. CRASH



NOEWALK FIRST TAXING DISTRICT
NOT TO SCALE

REVISED - INSPECTED 3/22/95 S.R.
 INSPECTED 2/28/20 J. CHAI




First Young Product - Norwalk

Insp = 28/90

Treatment - Pump Room:

John W. Craigy D.D. Esq.

INSULATED/REVISED 3/22/95 S. KUBBINS



DATE: 3/22/93 REVISED 5.8.93UTILITY/SOURCE(S): First Towing District - Norwalk / Hiker FeeINSPECTED WITH: Bill LaheyRATE OF WATER FLOW: effluent - 6.6 MGD (Insd / does not limit feed pumps)STAND BY POWER/CONDITION: 2 GENERATORS - #1 OUTSIDE TESTED WEEKLY AUTOSTART, #2 IN WAREHOUSE, BACKUPTYPE OF FEEDER: chem. metering pumpALTERNATE: same parts & motorRATE OF DOSAGE: (SPECIFY) 4 mg/LPOINT OF INJECTION: collection box - after filterSAMPLING POINT: amt. eff. sink - chem. well FREQUENCY OF TESTING: BI-WEEKLY

TESTING EQUIPMENT/CONDITION:

SAFETY EQUIPMENT (TYPE & CONDITION): shield, gloves, apronSCALES: amt. & kind of chem. on hand: zinc phosphate (shan-norox)COMMENT: mixer on hand2 - 55 gal. dau tanks
12 - 50 lb. bags on table in treatment room
55 - 50 lb. bags in warehouseTYPE OF FEEDER: BIF CHEMICAL METERING PUMPALTERNATE: SPARE PARTS & MOTORRATE OF DOSAGE: (SPECIFY) 10-11 mg/LPOINT OF INJECTION: PLANT INFLUENT PRIOR TO VENTURI METERSAMPLING POINT: PH MONITORED IN MIXING BASIN FREQUENCY OF TESTING: CONTINUOUS READING IN CONTROL ROOM

TESTING EQUIPMENT/CONDITION:

SAFETY EQUIP. (TYPE & CONDITION): EYE WASH, SHOWER, GLOVES, APRON, SHIELDSCALES: NONE AMT. & KIND OF CHEM. ON HAND: 1500 GAL IN 4300 GAL BRKCOMMENT: STORAGE TANK TRANSFERS TO360 GAL DAY TANKTYPE OF FEEDER: CHEM. METERING PUMPALTERNATE: SPARE PARTS & MOTORRATE OF DOSAGE: (SPECIFY) 0.1 mg/LPOINT OF INJECTION: AFTER SEDIMENTATIONSAMPLING POINT: _____ FREQUENCY OF TESTING: _____

TESTING EQUIPMENT/CONDITION:

SAFETY EQUIP. (TYPE & CONDITION): GLOVESSCALES: _____ AMT. & KIND OF CHEM ON HAND: 2 DRUMSCOMMENT: FILTRATION AID - NON-IONIC EMULSION POLYMER

GENERAL COMMENTS:

1 DRY CHEM. FEEDER SET-UP FOR CARBON - NOT USED

Comment on Records:

... also indicator is greater than main press. and there is


DATE: 2/26/90 3/22/95 S. EBBING REVISEDUTILITY/SOURCE(S): First Towing District - Norwalk Cable CarsINSPECTED WITH: Bill LaheyRATE OF WATER FLOW: effluent - 6.6 MGD Insp. (paces post trmt. feed pumps)STAND BY POWER/CONDITION: 2 GENERATORSTYPE OF FEEDER: parallel chem. meter pumps - only 1 used @ a time - alt. every 2 wks.ALTERNATE: same parts + motor*RATE OF DOSAGE: (SPECIFY) 3000 MG ≈ 4.3 mg/LPOINT OF INJECTION: collection chamber between filters #2 and #3SAMPLING POINT: trmt. effl. - clarewell FREQUENCY OF TESTING: at least weeklyTESTING EQUIPMENT/CONDITION: "SAFETY EQUIPMENT (TYPE & CONDITION): smell gloves, IRON, SHOWER, EYEWASHSCALES: noneCOMMENT: AMT. & KIND OF CHEM. ON HAND: 23% hydrofluoric acid
2,000 gal. bulk storage tank in warehouse
- pumped flow to 50 gal. day tank
(1500 gal. loads delivered)TYPE OF FEEDER: parallel w/t 11 notch chlorinators (both in use at same time - gravity water flow)ALTERNATE: same parts (serviced twice / yr.) to 4 notch / 2 parallel burners avail. - never used*RATE OF DOSAGE: (SPECIFY) 1500 MG ≈ 1.8 mg/LPOINT OF INJECTION: 2 mi. lines - into collection box after filtersSAMPLING POINT: trmt. effl. sink - clarewell FREQUENCY OF TESTING: CONTINUOUSTESTING EQUIPMENT/CONDITION: March 17SAFETY EQUIP. (TYPE & CONDITION): same as above - DMS 2 foot air tanks - warehouse with rimSCALES: 2 scales - 4 cub. per scale AMT. & KIND OF CHEM. ON HAND: 150 cylinder - chlorine gas
12 m 1 andCOMMENT: also cylinder 1 ester hit on road
+ automatic switchover after 5 (volts)
- press. gauge monitor (25 ora. red when down to 1/4 ft)
- all tanks chained in placeTYPE OF FEEDER: BIF chem. metering pumpALTERNATE: same parts + motor*RATE OF DOSAGE: (SPECIFY) 7.5 mg/LPOINT OF INJECTION: collection boxSAMPLING POINT: trmt. effl. sink - clarewell FREQUENCY OF TESTING: CONTINUOUSTESTING EQUIPMENT/CONDITION: pH - each probe (calibrated daily)SAFETY EQUIP. (TYPE & CONDITION): same as aboveSCALES: none AMT. & KIND OF CHEM. ON HAND: calcium hydroxide 50%
300 gal. bulk storage tank in warehouseCOMMENT: - gravity flow to 360 gal. day tank
- 500 gal. loads deliveredGENERAL COMMENTS:

Comment on Records: - ... that indicator is greater than main press. and there is

9-6-88
REVISED 4/5/95 S. Robbins



Norwalk - First Taxing District John W. Czaja OHS Engr.

①



Norwalk - First Taxing District
John W. Czaja DOHS Engr.

TREATMENT STATION



4-5775
7-6-88

Page: 1 of 3

Leys IR

UTILITY/SOURCE(S): Norwalk - First Towing District / Laune #2 and Laune #1 & #2 (bnd)

INSPECTED WITH: FRANCO CHIEFFALO and Bill Lahou

RATE OF WATER FLOW: vertical turbine → 1.8 MGD or 2.5 MGD - from clear well

STAND BY POWER/CONDITION: yes / 2 diesel 225 KW each / good (under service contract)
-will power everything except opening #1 & #2

TYPE OF FEEDER: PENWALT V match 200 bnd

ALTERNATE: parts

RATE OF DOSAGE: (SPECIFY) 25 lbs / MG 0.9 ppm

POINT OF INJECTION: basement of treatment station - after flow venturi

SAMPLING POINT: SINK @ first station - from dist. FREQUENCY OF TESTING: daily

TESTING EQUIPMENT/CONDITION: was not checked

SAFETY EQUIPMENT (TYPE & CONDITION): SCOTT AIR PACK - pres. tube (PANA plant, gas detector)

SCALES: yes - each cal on separate scale AMT. & KIND OF CHEM. ON HAND: 2-15#10 cylinders

COMMENT: Particulars are with exterior switch, for mounted on wall near river - OK

TYPE OF FEEDER: (2) - BIF - proportional to flow, located on flow meter in station

ALTERNATE: parts

RATE OF DOSAGE: (SPECIFY) 1000 lbs day tank - 1500 lbs day tank

POINT OF INJECTION: same as above

SAMPLING POINT: same as above FREQUENCY OF TESTING: daily

TESTING EQUIPMENT/CONDITION: checked @ filter plant

SAFETY EQUIP. (TYPE & CONDITION): GLOVES, APRON, MASK, SHOES, EYE - 100% tank - rubber lined

SCALES: day tank on balance scale AMT. & KIND OF CHEM. ON HAND: 100 ml tank storage
50 gal. day tank

COMMENT: 25% hydrofluoric acid (acidulation)

TYPE OF FEEDER: 2 - lead lining - prop. to flow

ALTERNATE: parts

RATE OF DOSAGE: (SPECIFY) 2 ppm 10 ml / 10 MAX

POINT OF INJECTION: same as above

SAMPLING POINT: same as above FREQUENCY OF TESTING: daily

TESTING EQUIPMENT/CONDITION:

SAFETY EQUIP. (TYPE & CONDITION): GLOVES APRON MASK

SCALES: AMT. & KIND OF CHEM. ON HAND:

COMMENT: WATER HARD-PLUMBED - AIR GAP

GENERAL COMMENTS:

Comment on Records:

Chlorine Gas: Check to see that injector is greater than main press. and
Cl gas cylinder press. Check cylinder arrangement.

Specify type of rate of dosage, instantaneous, daily, weekly, etc. also

chlorine

fluoride

SHAN - NO - CORA
zinc - polyphosphate

INSPECTION OF
AIR STRIPPING/CAC FILTRATION/PRESSURE FILTRATION FACILITIES

4/5/77
Date: 1-

Page 3 of 3

UTILITY: Norwalk First District Water Dept.
INSPECTED WITH: FRANCIS CHIEFFARI, Bill Lahan INSPECTED BY: S. ROBBINS
STANDBY POWER/CONDITION: yes/good FREQUENCY EXERCISED/UNDER LOAD: under service contract twice/year

AERATION TOWER

COLUMN HEIGHT: 36' WIDTH: 11' PACKING DEPTH: 23'
TYPE OF PACKING: No. 1 Jagary Tri-packs PROPER SCREENING: yes
TYPE/SIZE OF BLOWER (cfm/Quantity): 29,000 cfm
RATE OF WATER FLOW: approx. given 10-11-88 for 2600 gpm
MAXIMUM RATE OF WATER FLOW (Design): 2500 gpm AIR TO WATER RATIO: 77.5 : 1
CHLORINATION POINT: after clearwell SAMPLING LOCATION: infl. and effl. of tower
CLEARWELL SIZE: 750,000
BOOSTER PUMPS CAP./QUANTITY: 2-18 MGD and 1-2.5 MGD
COMMENT: tower looked in good condition (levels of VOC's not low)

CAC/PRESSURIZED FILTER

TYPE OF FILTER: _____
CARBON: MANUFACTURER: _____ CARBON MEDIA I.D. NO. _____
PREFILTER/DESCRIPTION: _____
RATE OF WATER FLOW: _____ MAXIMUM RATE OF WATER FLOW (Design): _____
AMOUNT OF MEDIA (ft³): _____ SURFACE AREA OF FILTER (ft²): _____
CONTACT TIME (Max.): _____ (Min.): _____
FLOW RESTRICTION DEVICE: _____
FILTER FLOW SCHEMATIC (include source, filters, sampling tap, meters and storage): _____

FREQUENCY OF MEDIA REPLACEMENT: _____ DATE OF LAST MEDIA REPLACEMENT: _____
HOW IS MEDIA REPLACEMENT DETERMINED: _____
BACKWASH CAPABILITIES (Yes/No) FREQUENCY: _____
BACKWASH RATE: _____ WHERE DISCHARGED: _____
DEP DISCHARGE PERMIT #: _____
SAMPLING LOCATION: _____ SAMPLING FREQUENCY (Filter Effl.): _____
COMMENT: _____

PK/ch (ee)

HYDRO GROUP, INC.
ENVIRONMENTAL PRODUCTS DIVISION

Packed Column Air Stripper
Production Specifications

I. Customer's Name: First Taxing District Water Dept.
Installation Location: Norwalk, CT
Customer Order Number: Contract W3-84B

II. Hydro Group Production Number: 2342-86

III. Column:

1. Drawing Number: 16B1554
2. Capacity: 1750 gpm
3. Size: 11' dia x 36' high
4. Inlet Pipe Size: 12" Outlet Pipe Size: 12"
5. Material: 6061-T6 Aluminum
6. Remarks:

IV. Packing:

1. Type: No. 1 Jaeger Tripacks
2. Nominal Size: 2"
3. Packing Depth: 23'
4. Packing Material: Polypropylene
5. Packing Support Type: Fiberglass grid

V. Liquid Distributor:

1. Distributor Type: Drilled orifice
2. Redistributor: Ring type

VI. Blower:

1. Make & Model: Barry Blower, Model 445 VCR
2. Capacity: 3,400 CFM @ 4" SP
3. Motor: 20 HP, 230/460 Volt, 3 ph 60 c;
4. Type of Motor: ODP
5. Electrical Control: Interconnected with well pumps

VII. Anchoring Arrangement:

1. Type: Single base ring
2. Number of Bolts: 24 @ 3/4" dia

VIII. Mist Eliminator:

1. Type: Polypropylene mesh pad with 304 grids
2. Thickness: 6"


Norwalk First District Water Department

REVISED 4/5/93 S. KEBBINS


Ins. 9/16/92

John W. (Ezra) - DHS, Engr.

West Rocks High Service Pump Station:




West Rock Elevated Tank:




both tanks serve West Rocks High Service zone

Bayne Street Standpipe:




Elbert Street Tank (Water Ave):



low pressure zone

SILVERLINE CROSSING CONDENS



Norwalk First District Water Department


REVISED 4/5/95 C KOBINS

Insp. 9/16/92

John W. Goggin - DHS, Eng


Spring Hill Elevated Tank:

(high pressure zone)




Spring Hill Standpipe:

(low service zone)



Spring Hill Pump Station:

(Grandview Ave. property)



IF RESID. IS < 0.3

FARTHEST POINT IN DISTRIB.,

CHLORINE IS FED. TIED

ELECTRICALLY TO PUMPS

Schematic - Not to Scale

Date: _____

UTILITY/SOURCE(S): NORWALK FIRST TAX DISTRICT - SPRING HILL PUMP STATIONINSPECTED WITH: FRANCO CHIEFFALORATE OF WATER FLOW: 850 GPMSTAND BY POWER/CONDITION: LP GENERATOR / GOOD WILL RUN BOTH PUMPSTYPE OF FEEDER: LMI CHEMICAL METERING PUMPALTERNATE: PARTS IN STATIONRATE OF DOSAGE: (SPECIFY) SOLUTION 50/50 \approx 0.8 mg/lPOINT OF INJECTION: STATION DISCHARGE LINESAMPLING POINT: SINK IN STATION FREQUENCY OF TESTING: DAILY

TESTING EQUIPMENT/CONDITION: _____

SAFETY EQUIPMENT (TYPE & CONDITION): EYEWASH GLOVES SODIUMSCALES: NONE AMT. & KIND OF CHEM. ON HAND: 15% HYPOCHLORITECOMMENT: 35 GAL DAY TANK WITH MIXER 5-55 GAL DRUMS ON HAND

TYPE OF FEEDER: _____

ALTERNATE: _____

RATE OF DOSAGE: (SPECIFY) _____

POINT OF INJECTION: _____

SAMPLING POINT: _____ FREQUENCY OF TESTING: _____

TESTING EQUIPMENT/CONDITION: _____

SAFETY EQUIP. (TYPE & CONDITION): _____

SCALES: _____ AMT. & KIND OF CHEM. ON HAND: _____

COMMENT: _____

TYPE OF FEEDER: _____

ALTERNATE: _____

RATE OF DOSAGE: (SPECIFY) _____

POINT OF INJECTION: _____

SAMPLING POINT: _____ FREQUENCY OF TESTING: _____

TESTING EQUIPMENT/CONDITION: _____

SAFETY EQUIP. (TYPE & CONDITION): _____

SCALES: _____ AMT. & KIND OF CHEM. ON HAND: _____

COMMENT: _____

GENERAL COMMENTS: _____

Comment on Records:

_____ that the infector is greater than main press. in 1 hour